

JOINT HOUSE RULES POLICY ROOF RULES

All persons accessing the roof must understand and comply with these rules.

- 1. Access to the roof is restricted to minimize traffic on the membrane.
 - 1.1 Access to the roof is controlled by card reader. A card reader also controls return access from the roof.
 - 1.2 Security will only allow access upon approval of Data Center Operations Staff.
- 2. Sign the Roof Access Log before accessing the roof and after leaving.
- 3. No smoking is allowed on the roof.
- 4. Stay on designated walkways as much as possible.
 - 4.1 Limit traffic to areas necessary to conduct work.
- 5. Wear footwear with good traction, as the roof can become slippery.
 - 5.1 Do not wear high-heeled shoes or any form of spiked-sole shoes on the roof.
- 6. Handle materials carefully to avoid damage to the roof.
 - 6.1 Protect staging areas where material is being hoisted up to the roof with both a layer of 2" extruded polystyrene, covered with 5/8" plywood.
 - 6.2 Transport heavy materials on a cart or hand truck resting on 5/8" plywood. Pneumatic-tired hand trucks may be run directly on the walkways, so long as the load they are transporting is less than 100 pounds.
- Exercise caution when working on the roof.
 - 7.1 Prevent tools and materials from damaging the membrane.
 - 7.2 Do not place tools and materials directly on the membrane. Lighter materials may be placed on rubber mats. Heavier materials shall be placed on a minimum of either 5/8"x4'x4' plywood or 2"x4'x4' extruded polystyrene.
 - 7.3 Utilize 5/8"x4'x4' plywood at the base of any ladders to prevent the ladder from damaging insulation.
- 8. Use blankets or other materials to prevent solder, molten metal, or metal shavings from coming in contact with the membrane.
 - 8.1 Follow appropriate hot work procedures, including building hot work permit.
- 9. Do not allow sharp metal objects (nails, screws, cut metal, etc.) to come in contact with the membrane.
- 10. Do not step on or rest heavy loads on pipe insulation.
 - 10.1 Damage to the insulation jacket allows the insulation to become wet and the heat trace to fail.
 - 10.2 Use ladders or step stools to access humidifiers and condensers, with plywood at ladder base.
- 11. Practice good housekeeping.
 - 11.1 Remove all debris generated from the work and dispose of it off site.
 - 11.2 Leave the roof cleaner than found.
- 12. Immediately report any roof or other problems to Data Center Operations Staff.
 - 12.1 After cleaning up the work area, inspect the membrane for any tears.
- 13. Failure to comply with these Roof Rules may result in denial of access to the roof.

Revision 2 Page 1 of 1